




TECH BULLETIN #116

TECH SUPPORT: phone: 800-543-6618, Prompt #2 email: service@procutusa.com
All Pro-Cut technical bulletins: www.procutusa.com/bulletins.aspx
www.procutusa.com  www.facebook.com/procutusa

Performance Plus Insert Update

The Pro-Cut Performance Plus Inserts (50-778) now have a series of “dots” on them to designate cutting tip edge position. This should make it easier in determining which edge was used to cut the rotors.

Use the **50-776** T8 Screws and the **37-740** T8 Torx Wrench

Position 1 is represented by a “Rotor Icon”.

Position 2 is represented by a pair of notches.

Position 3 is represented by a pair of notches and a dot.



Contact the Pro-Cut Service Department at 800.543.6618, Prompt #2, with any questions.

PRO-CUT INTERNATIONAL is the world leader in rotor matching systems and on-car brake lathes.
The company is located in West Lebanon, NH.